



MARITIME INDUSTRY AUTHORITY

18 January 2017

MARINA ADVISORY

NO. 2017-02

Series of 2017

TO : All Shipowners/Bareboat Charterers/Ship Operators/Shipmanagers of the Philippine Registered Ships Engaged in the International Trade and Other Concerned Entities

SUBJECT : International Maritime Organization (IMO) Safety of Navigation 1/Circular 263 dated 23 October 2007 on the Guidance set forth Under Section 1.9 and 1.14 on Routeing Measures Other than Traffic Separation Schemes

Notice is hereby given to all concerned that according to the result of the 83rd Maritime Safety Committee Meeting which was held on 03-12 October 2007, it adopted in accordance with the provisions of Resolution A.858(20) the new routeing measures other than traffic separation schemes, as reflected in the IMO Safety of Navigation 1/Circular 263 issued on 23 October 2007. Said Safety Circular is attached as an integral part of this MARINA Advisory.

In view thereof, all shipowners, bareboat charterers, ship operators, ship managers and other concerned maritime entities are required to abide by the said IMO Circular.

Any queries relating to this Advisory should be directed to:

1. MARINA Administrator

Telephone Nos. : +63 2 523 9078 and +63 2 526 0971

Address : Room 401, 4/F Parkview Plaza
984 Taft Avenue corner T.M. Kalaw St.
Ermita, Manila, Philippines

Email Address : oadm@marina.gov.ph


2. Overseas Shipping Service-MARINA

Telephone No. : +63 2 525 7890

Address : Room 304, 3/F Parkview Plaza
984 Taft Avenue corner T.M. Kalaw St.
Ermita, Manila, Philippines

Email Address : oss@marina.gov.ph

For strict compliance and guidance of all concerned.


Mr. MARCIAL Q.C. AMARO III, PhD
Administrator